

Detailed Equipment Information

Print

Download All Photos

DEVELON DL220-7 / WLR

- [General Appearance](#)
 - [Control Station](#)
 - [Engine](#)
- [Drivetrain](#)
 - [Brakes](#)
 - [Hydraulics](#)
- [Specialty](#)
 - [Chassis](#)
 - [Deficiencies](#)

GENERAL APPEARANCE

[Back To Top](#)

SERIAL NUMBER / VIN	DHKCWLDP5050525	
SELLER REFERENCE NUMBER	Seller Reference or Fleet Number:	
TIRES/ UNDERCARRIAGE	Percentage Rating:, 60	
HOUR METER / ODOMETER	0 Not Available	
CONDITION	Overall Condition for Age:, Good	
FEATURES	Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Requires AdBlue, 102 in Bucket, 20.5R25 Tires	



1 of 9



Photo 1



Photo 2



Photo 3

CONTROL STATION

[Back To Top](#)

CONTROL STATION

Cab Type, Enclosed Cab, Air Conditioner,
Rear View Camera, Air Ride Seat

LIMITED FUNCTION CHECK

The main components are in place and
operational as noted.



Photo 1



Photo 2



Photo 3

ENGINE

ENGINE

No US EPA Label Present Requires AdBlue

[Back To Top](#)

LIMITED FUNCTION CHECK

After jump starting, the engine ran.



Photo 1



Photo 2



Photo 3


DRIVETRAIN

LIMITED FUNCTION CHECK

The drivetrain was operational.

[Back To Top](#)





BRAKES

BRAKES

The brakes are operational.

[Back To Top](#)

HYDRAULICS

LIMITED FUNCTION CHECK

The hydraulic system was operational.

[Back To Top](#)



SPECIALTY

FRONT ATTACHMENT

Front Attachment Details, 102 in Bucket
Type: Bucket

[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6
- Photo 7
- Photo 8

CHASSIS

TIRES

20.5R25 Tires

[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6
- Photo 7

DEFICIENCIES

DEFICIENCIES	Deficient Components/Systems Include but are not limited to: Control Station Section illuminated warning lights
--------------	---

[Back To Top](#)

DISCLAIMER

General

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes