

Detailed Equipment Information

[Print](#)

[Download All Photos](#)

DOOSAN DD100 / CTR



- [Find it in Yard](#)
- [General Appearance](#)
- [Control Station](#)
- [Engine](#)
- [Drivetrain](#)
- [Hydraulics](#)
- [Chassis](#)
- [Undercarriage](#)
- [Specialty](#)

FIND IT IN YARD

ASSIGNED LANE AND SPOT	Located in Lane 2 Spot 17
------------------------	---------------------------


[Back To Top](#)

GENERAL APPEARANCE

SERIAL NUMBER / VIN	DWGCZACKN1010129	
SELLER REFERENCE NUMBER	Seller Reference or Fleet Number:	
TIRES/ UNDERCARRIAGE	Percentage Rating:, 70	
HOUR METER / ODOMETER	799 hrs	
CONDITION	Overall Condition for Age:, Very Good	
FEATURES	Located in Lane 2 Spot 17, Enclosed Cab, Air Conditioner, Rear View Camera, 129 in Wide PAT Blade, 27.5 in Single Grouser Track Shoes, 2 Cylinder Multi-Shank Ripper	

[Back To Top](#)





CONTROL STATION

[Back To Top](#)

CONTROL STATION	Cab Type: Enclosed Cab, Air Conditioner, Rear View Camera
LIMITED FUNCTION CHECK	The main components are in place and operational as noted.

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6
- Photo 7

ENGINE

[Back To Top](#)

LIMITED FUNCTION CHECK	The engine started and ran.
-------------------------------	-----------------------------

- Photo 1

DRIVETRAIN

[Back To Top](#)

LIMITED FUNCTION CHECK	The drivetrain was operational.
-------------------------------	---------------------------------

- Photo 1
- Photo 2

HYDRAULICS

[Back To Top](#)

LIMITED FUNCTION CHECK	The hydraulic system was operational.
-------------------------------	---------------------------------------

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6
- Photo 7

CHASSIS

[Back To Top](#)

FRONT ATTACHMENT	129 in Wide PAT Blade
-------------------------	-----------------------

- Photo 1
- Photo 2
- Photo 3

UNDERCARRIAGE

[Back To Top](#)

UNDERCARRIAGE	27.5 in Single Grouser Track Shoes
----------------------	------------------------------------

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6

SPECIALTY**REAR ATTACHMENT**

Number of Ripper Cylinders: 2 Cylinder

Ripper Type: Multi-Shank Ripper

[Back To Top](#)

-  Photo 1
-  Photo 2
-  Photo 3

DISCLAIMER**General**

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes