2023 DOOSAN DL420

UNIT: DWGCWLECCN1010340





UNIT SPECS

Customer	PNC Equipment Finance

LOCATION

R.B. Everett
8211 Red Bluff Rd
Pasadena, TX 77507

GENERAL APPEARANCE

Year
2023

Make
Doosan

Model
DL420

Unit Number
208894

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Body Panels
No visible damage or missing components.

Fenders
Left front damaged, Right front damaged

Steps
No visible damage or missing components.

Hand Rails
No visible damage or missing components

Exterior Lights
2 Inoperable / damaged / missing

Cab/Canopy Overhead Structural Framework
No visible damage

Serial Number / VIN
DWGCWLECCN1010340

Serial Number
DWGCWLECCN1010340

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Current Safety Manual
No

Current Operator/Maintenance Manual
No

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
Back window seal

Cab Doors
Missing cover on driver's door

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
The gauge registers in the operating range.

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera

Hour Meter /Odometer Usage Reading (Start)
4796.7 hrs

Hour Meter / Odometer
4797 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

DRIVETRAIN

Transmission
Rating:
Good

Transfer Case / Drop Box
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Has residue on it
Rating:
Fair

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders
Rating:
Good

Steering Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Tilt Linkage
Rating:
Good

Tilt Linkage Pins And Bushings
Rating:
Good

Quick Coupler To Arms Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

Articulating Center Pins
Rating:
Good

Brake Type
Hydraulic

Master Cylinder
Rating:
Good

Brake Lines/Hoses
Rating:
Good

Park Brake
Rating:
Good

Limited Function Check - Brakes
The brake system functioned, stopping and holding the machine.

Frame Condition
Rating:
Good

Left Front Tire
Triangle Tb516 26.5R25 32/32" Tread Depth
Rating:
Good

Left Rear Tire
Triangle Tb516 26.5R25 28/32" Tread Depth
Rating:
Good

Right Rear Tire
Triangle Tb516 26.5r25 27/32" Tread Depth
Rating:
Fair

Right Front Tire
Triangle Tb516 26.5r25 27/32" Tread Depth
Rating:
Fair

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Front Attachment Details, Quick Coupler Type: Hydraulic Coupler, 129 in Bucket Type: Bucket, Forks, Blade

Loader Bucket Condition
Rating:
Good

Loader Bucket Cutting Edge
No visible damage or missing components
Rating:
Good

Loader Quick Coupler
Operational
Rating:
Good

Forks
Rating:
Good

CHECK SECTION

RECONDITIONING

Cab Doors: Missing cover on driver's door

Paint: Damage

Fenders: Left front damaged, Right front damaged

Exterior Lights: 2 Inoperable / damaged / missing