

## ITEM DETAILS - 2021 Doosan DL320-7

Tuesday, March 03, 2026

### DETAILED EQUIPMENT INFORMATION

A qualified Ritchie Bros. employee collected detailed equipment information and performed functional tests on the key components of this asset.

#### General Appearance

Serial Number / VIN: DWGCWLEDKM1010074

Seller Reference Number: Seller Reference or Fleet Number:

Tires/ Undercarriage: Percentage Rating:

Hour Meter / Odometer: 277 hrs

Features: Enclosed Cab, Air Conditioner, Air Ride Seat, Hydraulic Coupler, 4 cyd 113 in Bucket, 23.5R25 Tires



#### Control Station

Control Station: Cab Type, Enclosed Cab, Air Conditioner, Air Ride Seat

Limited Function Check: The item was not operational. The main components could not be operationally checked. Machine is not detecting the key fob and is preventing start up



#### Engine

Limited Function Check: The engine could not be started.



---

### Drivetrain

**Limited Function Check:** The drivetrain could not be operationally checked.



---

### Brakes

**Brakes:** The brakes could not be operationally checked.

---

### Hydraulics

**Limited Function Check:** The hydraulic system could not be operationally checked.



---

### Specialty

**Front Attachment:** Front Attachment Details, Quick Coupler Type: Hydraulic Coupler, 4 cyd 113 in Bucket Type: Bucket



---

### Chassis

Tires: 23.5R25 Tires



---

### Deficiencies

Deficiencies: Deficient Components/Systems  
Include but are not limited to: Control Station  
Section

---

## DISCLAIMER

### General

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

### Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

### Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes